

| GS1 DataBar Readiness Survey | | | | | | | |
|--|------------------------------------|---|-----------|--------|--------------|-----------------------|----------------------|
| Note: For Scanner type field put in #: For region field: place "X" where sold | | | | | | | |
| GS1 DataBar Ready Scanners | | | | | | | |
| | | Scanner Type | Region | | | | |
| Company Name | Model | 1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear | US/Canada | Europe | Asia Pacific | South & Latin America | Middle East & Africa |
| HP | HP Laser Barcode Scanner (EY022AA) | HH Linear | X | X | X | | X |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Scanners requiring GS1 DataBar Upgrade | | | | | | | |
| | | Scanner Type | Region | | | | |
| Company Name | Model | 1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear | US/Canada | Europe | Asia Pacific | South & Latin America | Middle East & Africa |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Scanners which can not be upgraded to GS1 DataBar (RSS) | | | | | | | |