

GS1 DataBar Readiness Survey							
Note: For Scanner type field put in #: For region field: place "X" where sold							
GS1 DataBar Ready Scanners							
Company Name	Model	Scanner Type	US/Canada	Europe	Asia Pacific	South & Latin America	Middle East & Africa
		1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear 5. Fixed Mount Linear 6. Fixed Mount Omni 7. Fixed Mount Imager					
Motorola	MS-3223	6	X	X	X	X	X
Motorola	LS 2208	4	X	X	X	X	X
Motorola	LS 1203	4	X	X	X	X	X
Motorola	DS670X	3	X	X	X	X	X
Motorola	LS920X	2	X	X	X	X	X
Motorola	LS7707	1	X	X	X	X	X
Motorola	LS7808	1	X	X	X	X	X
Motorola	M200X	2	X	X	X	X	X
Motorola	LS3008	4	X	X	X	X	X
Motorola	LS34XX	4	X	X	X	X	X
Motorola	LS35XX	4	X	X	X	X	X
Motorola	DS34XX	3	X	X	X	X	X
Motorola	LS42XX	4	X	X	X	X	X
Motorola	MS-32xx	6	X	X	X	X	X
Motorola	MS-22xx	5	X	X	X	X	X
Motorola	MS-12xx	5	X	X	X	X	X
Motorola	MS-954	5	X	X	X	X	X
Motorola	MS-44xx	7	X	X	X	X	X
Motorola	SE-95x	5	X	X	X	X	X
Motorola	SE-12xx	5	X	X	X	X	X
Motorola	SE-22xx	5	X	X	X	X	X
Motorola	SE-32xx	6	X	X	X	X	X
Motorola	SE-44xx	6	X	X	X	X	X

Motorola	SE-45xx	7	X	X	X	X	X
Motorola	SE-15xx	5	X	X	X	X	X
Motorola	SE-6700	6	X	X	X	X	X
These are scan engines not finished product							
<b>Scanners which can not be upgraded to GS1 DataBar (RSS)</b>							
P370							
P470							
P360							
P460							
<b>Scanners requiring GS1 DataBar Upgrade</b>							
		<b>Scanner Type</b>	<b>Region</b>				
Company Name	Model	1. Omni Hi speed checkout, 2. Presentation,3. HH Imager, or 4. HH Linear	US/Canada	Europe	Asia Pacific	South & Latin America	Middle East & Africa
Not Applicable							